

AD-A061 701

TELEDYNE CAE TOLEDO OHIO

ADVANCED TURBINE ENGINE GAS GENERATOR (ATEGG) FRACTOGRAPHY OF C--ETC(U)

F33657-76-C-0215

NOV 78 D F GRAY

TCAE-1567-VOL-4

F/G 11/6

NL

UNCLASSIFIED

1 OF 1  
AD  
A061 701

AFAPL-TR-77-30-VOL-4



END  
DATE  
FILED  
2-79  
DDC

ADA061701

DDC FILE COPY

LEVEL *2*

2


DAVID F. GRAY

TELESTIMES  
EXPERIMENTAL  
SATELLITE

NOVEMBER 1978

Final Report

1 October 1976 - 30 June 1978



10

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

UNCLASSIFIED

LEVEL II

2

SECURITY CLASSIFICATION OF THIS PAGE (When D

19 REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER AFAPL-TR-77-30-Vol. IV, VOL-4	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER 9 Crept.
4. TITLE (and Subtitle) ADVANCED TURBINE ENGINE GAS GENERATOR (ATEGG) FRACTOGRAPHY OF CAST NICKEL BASE SUPERALLOYS		5. TYPE OF REPORT & PERIOD COVERED Final R&D Materials 1 Oct 1975 - 30 June 1978
7. AUTHOR(s) David F. Gray	15	6. PERFORMING ORG. REPORT NUMBER Report No. 1567
9. PERFORMING ORGANIZATION NAME AND ADDRESS Teledyne CAE 1330 Laskey Road Toledo, Ohio 43612	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 63216F 681B0105 16 (12) 01	
11. CONTROLLING OFFICE NAME AND ADDRESS Air Force Aero Propulsion Laboratory Turbine Engine Division (TBP) Wright-Patterson Air Force Base, Ohio 45433	11	12. REPORT DATE November 1978
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) 12 28p.	13. NUMBER OF PAGES 27	
15. SECURITY CLASS. (of this report) Unclassified		
15a. DECLASSIFICATION/DOWNGRADING SCHEDULE 14 TCAE-1567- VOL-4		
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Turbine Blades Fractography Cast Nickel Base Superalloys      Rene' 80 IN-100 Low Cycle Fatigue		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report documents Teledyne CAE's efforts to correlate the fracture surfaces of cast nickel-base superalloys to known conditions of low cycle fatigue testing (strain range partitioning). Rene' 80 and IN-100 low cycle fatigue test specimens (supplied by NASA-Lewis and TRW materials laboratories) were examined by means of scanning electron microscope (SEM). The fractography obtained with the SEM can be compared to actual engine component failures, and will provide strong indications of the metal temperature.		

DD FORM 1 JAN 73 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED  
SECURITY CLASSIFICATION OF THIS AGENT (When Data Entered)

78

78 405 711

LB

ABSTRACT (Cont'd.)

creep conditions, strain levels, and cycles imposed, during the events leading to component failure.

## FOREWORD

This R&D Materials report is submitted by Teledyne CAE, under contract F33657-76-C-0215. The effort was sponsored by the Air Force Aero Propulsion Laboratory (TBP), Air Force Systems Command, Wright-Patterson AFB, Ohio under Project 681B, Task Area 01, Work Unit 05 with Mr. T. Gingrich as Project Engineer. Mr. Stanley Mathews of Teledyne CAE was technically responsible for the work. The work span covered by this report is 1 October 1975 through 30 June 1978.


This report, Volume IV, combined industry and government version, is the final volume that documents work accomplished directly under the subject contract.

Volume I, Level I Performance, documents that work accomplished under the contract period October 1975 through July 1976. Part I is the government version, Part II is the industry version.

Volume II, Level II Performance, documents that work accomplished under the contract period July 1976 through March 1977. Part I is the government version, whereas Part II is the industry version.

Volume III, Final Technical Report, documents all technical work accomplished and information gained from contract initiation, 1 October 1975, through contract completion, 31 July 1978. As with Volumes I and II, it is published in two parts: Part I, government; Part II, industry.

ACCESSION NO.	
BTB	White Section
BDB	Buff Section
UNARMED	
JUSTIFICATION	
BY	
DISTRIBUTION/AVAILABILITY CODE	
REL	AVAIL. GEN/EX. SPECIAL
A	



## TABLE OF CONTENTS

	<u>Page</u>
OBJECTIVE	1
MATERIAL HISTORY	1
SUPPLEMENTARY INFORMATION	3
Grain Size	3
Porosity	3
Initiation Zone	3
Test Method	3
Test Data	3
SUMMARY OF FRACTOGRAPHY	3

## LIST OF ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
1	Test Specimen Configuration	2
2	Hysteresis Loops That Define the Fatigue Cycle Types	5
3	Scanning Electron Microscope - 100 Angstrom Depth of Field Resolution	5
4	Specimen 42U-PP-11	7
5	Specimen 8U-PP-7	8
6	Specimen INN 5-PP	9
7	Specimen INN 8-PP	10
8	Specimen INN 18-PP	11
9	Specimen INN-3-PP	12
10	Specimen INN 17-PP	13
11	Specimen INN 11-CP	14
12	Specimen 89U-PC-8	15
13	Specimen 26U-PC-8	16
14	Specimen INN-13-P	17
15	Specimen INN-9-CP	17
16	Specimen INN-12-CC	18
17	Specimen 121C-T-1	19
18	Specimen 123C-T-3	20
19	Specimen 25-C-1	21
20	Specimen 37U-C-7	22

## FRACTOGRAPHY OF CAST NICKEL BASE SUPERALLOYS

### OBJECTIVE

The purpose of this effort was to correlate the fracture surfaces of cast nickel base superalloys to known conditions of low cycle fatigue testing (strain range partitioning) to support Teledyne CAE's 555 gas generator turbine blade materials analysis.

### MATERIAL HISTORY

Through the courtesy of personnel at NASA-Lewis and TRW materials laboratories, Rene' 80 and IN-100 low cycle fatigue test specimens were obtained for scanning electron microscope examination. The purpose of the examination was to characterize the features of the fracture surfaces and relate them to the known failure conditions of testing. In turn, the information gained could then be applied to the analysis of failures experienced on service and development engine components.

The Rene' 80 specimens supplied by NASA-Lewis for the Teledyne CAE examination were the individually cast, tubular, hour-glass-shaped specimens with threaded ends as per NASA Drawing CB-300740, shown in Figure 1. The specimens were originally cast as solid bars, machined to the proper configuration, and then given the following heat treatment:

1218°C (2225°F)/2 hours vacuum/argon quench to room temperature

1093°C (2000°F)/4 hours vacuum/argon quench to room temperature

1052°C (1925°F)/4 hours vacuum, furnace cool in vacuum to 649°C  
(1200°F) within 1 hour, air cool to room temperature

843°C (1550°F)/16 hours vacuum/furnace cool to room temperature

The cast nickel base Rene' 80 specimens examined were vacuum tested at 871°C (1600°F) and 1000°C (1832°F). These specimens had the advantage of clean, oxide-free surfaces. They were taken from a group of specimens that had creep hold times included in that portion of the cycle that was tension, or compression, or both. Some other specimens had no creep hold at all. Tensile and creep-rupture specimens were also examined. Only eight specimens of the Rene' 80 were examined because several of the specimens that represented the failure conditions of interest were not available. These specimens had been used by TRW in their investigations. However, the specimens, with oxide free surfaces, that were examined were very valuable because they provided information at two temperatures and a fair spectrum of failure conditions and characteristics. A full NASA report\* (Reference) has been published on this fatigue work.

### REFERENCE

Kurtovich, C.S., "Ultrahigh Vacuum, High Temperature, Low Cycle Fatigue of Coated and Uncoated Rene' 80", NAS CR-135003 (TRW-ER-78E1), April 1976.

**A** SURFACES AND P.D. OF THREADS  
 1. MUST BE CONCENTRIC, SQUARE & TRUE  
 WITHIN .0005" F.I.R.

2. 16/ALL OVER EXCEPT AS NOTED




Figure 1. Test Specimen Configuration

Cast nickel base IN-100 specimens (also per Figure 1) were also supplied by NASA-Lewis that had been tested in air at 926°C (1700°F). Some of these low cycle fatigue specimens had been tested with creep hold times in the tension or compression portion of the cycle, or both. Other specimens in this group had no creep hold times at all. No tensile or creep-rupture specimens were available from this group of specimens. The scanning electron microscope examination of these specimens proved to be equally valuable, because they did have oxide on the fracture surfaces, and because they were tested under controlled conditions. These fracture surfaces can be compared to actual engine component failures and provide strong indications of temperature, creep conditions, strain level and cycles to failure.

#### SUPPLEMENTARY INFORMATION

##### GRAIN SIZE

The grain size of the specimens examined was estimated to be 0.508 mm (0.020 in.) to 1.0 mm (0.040 in.), based on exterior visual measurements on specimens and estimates from photography included in the reference report.

##### POROSITY

Extensive shrinkage (microporosity) was seen on the fracture surfaces. This was particularly true of the Rene' 80 specimens.

##### INITIATION ZONE

Most of the specimens had multiple initiation sites, many of which were associated with microporosity.

##### TEST METHOD

The test method, except for tensile and creep-rupture, was axial low cycle fatigue. The specimens were 1/2 inch diameter cast hollow tubes. The gage area was hour-glass reduced to a wall thickness of 0.039-0.061 inch.

##### TEST DATA

The summary data for the specimens examined are given in Table 1. The data presented in the table have been reduced from the actual test data generated to illustrate the type and general magnitude of loading conditions. In this manner, the effect of the loading conditions is thought to be better understood with respect to the fracture surface characteristics. Figure 2 defines the load cycle sequence with respect to creep and specimen notation on the low cycle fatigue specimens.

##### SUMMARY OF FRACTOGRAPHY

All fracture surfaces were photographed by a scanning electronic microscope (Figure 3) at 400X for direct comparison of surface features with other specimens.

TABLE 1  
SUMMARY OF SPECIMEN TEST CONDITIONS


FIGURE NO.	MATERIAL & TEST CODE	TEST TYPE ***	TEST TEMP (°F)	TOTAL STRAIN RANGE (IN.)	TIME TO FAILURE (HRS.)	CYCLES TO FAILURE	APPROXIMATE TIME IN CREEP (HRS.)	TENSION/COMPRESSION
<u>RENE' 80*</u>								
3	8U-PP-7	PP	1832	.00247	5.0	22115	0/0	
2	42U-PP-11	PP	1600	.00296	58.0	217620	0/0	
11	26U-PC-8	PC	1832	.00409	19.1	10164	0/19	
10	89U-PC-11	PC	1832	.00579	4.9	187	0/5	
16	123C-T-3	Tensile	1600					
15	121C-T-1	Tensile	1832					
18	37U-C-7	Creep-Rup.	1600	40 KSI	2.1			
17	25U-C-1	Creep-Rup.	1832	30 KSI	0.7			
<u>IN-100**</u>								
7	INN 3-PP	PP	1700	.0092	.05	96	0/0	
8	INN 17-PP	PP	1700	.0113	.09	160	0/0	
6	INN 18-PP	PP	1700	.0064	.17	300	0/0	
5	INN 8-PP	PP	1700	.0049	.56	1000	0/0	
4	INN 5-PP	PP	1700	.0036	16.3	29400	0/0	
14	INN 12-CC	CC	1700	.0121	302.0	17	150/150	
12	INN 13-PC	PC	1700	.0058	87.3	139	0/87.3	
9	INN 11-CP	CP	1700	.0090	163.9	60	164/0	
13	INN 9-CP	CP	1700	.0041	159.3	1100	159/0	

27953  
Unclassified

\* TRW test specimen code.

\*\* NASA test specimen code.

\*\*\* See Figure 2 for description of test loading.



27954

Figure 2. Hysteresis Loops That Define the Fatigue Cycle Types.




Figure 3. Scanning Electron Microscope - 100 Angstrom Depth of Field Resolution.


The microscope was an International Scientific instrument having a depth of field resolution of 100 angstroms. Supplementary photographs are included at various magnifications to clarify various features of the individual specimens.

In the temperature range investigated, there was no major indication that the fracture surface characteristics changed between the Rene' 80 or IN-100 material when subjected to similar loading conditions. Except for the presence of oxide on the air tested IN-100, the fracture surface characteristics were also similar on vacuum tested and air tested surfaces.


The pp (see Figure 2 for notation) fracture surfaces were found to have definite striations and transgranular plane surfaces when tested in a total strain range of 0.5 percent or less, as shown in Figures 4, 5, 6, and 7. At greater than 0.5 percent total strain, the fracture surface tends to remain transgranular, but is less planar and seems to prefer the interdendritic zones, as seen in Figures 8, 9, and 10. Initiation at these higher strains may be associated with intergranular specimen surface separation (Figure 10), but slip plane formation is still evident in the interior metal at these higher strain rates, as can be seen in Figures 8 and 9.

When a creep hold is introduced into the cycle, such as during cc, pc, and cp loading, the low-profile dimpled, grain boundary rupture is generally more prevalent, as is evident in Figures 11, 12, and 13. These generated grain boundary voids tend to become less uniform in size with lower strains (greater number of cycles of failure), as can be seen by comparing Figures 12 and 13, and are probably the result of void coalescence with time, number of cycles, and grain orientation with respect to the loading direction. The presence of heavy surface oxides and surface contacts during reversed loading tends to obliterate some surface characteristics at times, as may be seen in Figure 14, 15, and 16. However, the general intergranular failure is still evident.

Tensile and short life creep-rupture surfaces are included for the reader to compare fracture surfaces, in Figures 17, 18, 19, and 20. It can be seen that tensile failures at 871°C (1600°F) and 1000°C (1832°F) are both dominated by transgranular rupture and tend to be associated with particulate phases, such as carbide. Short time creep-rupture tends to show evidence of grain boundary influence on the fracture surface, but at 871°C (1600°F) transgranular failure is still present as evidenced by the multiple slip planes in Figure 20.




27964




27965

Figure 4. Specimen 42U-PP-11 - Low Cycle Fatigue, PP Loading,  
Test Temperature - 1600°F Vacuum  
Material - Rene' 80  
Total Strain Range - 0.00296, 271,620 Cycles  
Top 400X, Bottom 1000X  
Transgranular Fatigue Striations




27961




27962

**Figure 5.** Specimen 8U-PP-7 - Low Cycle Fatigue, PP Loading  
Test Temperature - 1832°F Vacuum  
Material - Rene' 80  
Total Strain Range - 0.00247, 22115 Cycles  
Top 400X, Bottom 1000X  
Transgranular Fatigue Striations




27963




27975

Figure 6. Specimen INN 5-PP - Low Cycle Fatigue, PP Loading  
Test Temperature - 1700°F Air  
Material - IN-100  
Total Strain Range - 0.0036, 29400 Cycles  
Top 400X, Bottom 1000X  
Transgranular Fatigue




27970




27971

Figure 7. Specimen INN 8-PP - Low Cycle Fatigue, PP Loading  
Test Temperature - 1700°F Air  
Material - IN-100  
Total Strain Range - 0.0049, 1000 Cycles  
Top 400X, Bottom 50X  
Transgranular Fatigue




27968




27969

Figure 8. Specimen INN 18-PP - Low Cycle Fatigue, PP Loading  
Test Temperature - 1700°F Air  
Material - IN-100  
Total Strain Range - 0.0064, 300 Cycles  
Top 400X, Bottom 200X  
Dominant Transgranular (Interdendritic) Fatigue  
Note Some Slip Planes (Arrows)




27966  
Unclassified




27967  
Unclassified

Figure 9. Specimen INN-3-PP - Low Cycle Fatigue, PP Loading  
Test Temperature - 1700° Air  
Material - IN-100  
Total Strain Range - 0.0092, 96 Cycles  
Top 400X, Bottom 50X  
Dominant Transgranular (Interdendritic) Fatigue  
Note Some Slip Planes (Arrow).




**Figure 10.** Specimen INN 17-PP - Low Cycle Fatigue, PP Loading  
Test Temperature - 1700° Air, Material - IN-100  
Total Strain Range - 0.0113, 160 Cycles  
Top Left 400X, Top Right 200X, Bottom 1000X  
Dominant Transgranular Fatigue  
Intergranular Dimpled Ductile Rupture At Specimen  
Surface Initiation Points (Bottom)




27972

27973




27974

**Figure 11.** Specimen INN 11-CP Low Cycle Fatigue, CP Loading  
Test Temperature - 1700°F Air, Material - IN-100  
Total Strain Range - 0.009, 60 Cycles, Test Time 0 163.9 Hrs.  
Top Left 400X, Top Right 1000X, Bottom 400X  
Dominant Grain Boundary Dimpled Ductile Rupture in Creep  
Hold Fatigue.




27959




27960

Figure 12. Specimen 89U-PC-8 - Low Cycle Fatigue, PC Loading  
Test Temperature - 1832°F Vacuum  
Material - Rene' 80  
Total Strain Range - .00579, 187 Cycles  
Test Time - 4.9 Hrs.  
Top 400X, Bottom 1000X  
Dominant Grain Boundary Fatigue with Dimpled Ductile Rupture.




27957



27958

Figure 13. Specimen 26U-PC-8 - Low Cycle Fatigue, PC Loading  
Test Temperature - 1832°F Vacuum, Material - Rene'80  
Total Strain Range - 0.00409, 10164 Cycles  
Test Time - 19.1 Hrs., Top 400X, Bottom 1000X  
Dominant Grain Boundary Fatigue with Dimpled Ductile Rupture.  
Note Larger Dimple Size with Greater Number of Cycles  
(See Figure 12).



27955

Figure 14. Specimen INN-13-PC - Low Cycle Fatigue, PC Loading  
Test Temperature - 1700°F Air  
Material - IN-100, Total Strain Range - 0.0058, 139 Cycles  
Test Time - 87.3 Hrs., 1000X  
A Compression Dominated Hold can Damage The Grain Boundary  
Fatigue Indications, Particularly in an Air Environment.



27956

Figure 15. Specimen INN-9-CP - Low Cycle Fatigue, CP Loading  
Test Temperature - 1700°F Air  
Material - IN-100, Total Strain Range - 0.0041, 1100 Cycles  
Test Time - 159.3 Hrs., 400 X  
Reverse Loading Can Damage the Dimples Found in Grain Boundary  
Fatigue, But is Less Damaging in a Tension Hold  
Dominated Fatigue Load.







Figure 16. Specimen INN-12-CC - Low Cycle Fatigue, CC Loading  
Test Temperature - 1700°F Air  
Material - IN-100, Total Strain Range - 0.0121, 17 Cycles  
Test Time - 302 Hrs., Top 400X, Bottom 50X  
When the Number of Cycles is Low, Grain Boundary Indications  
(Dimples) are Still Discernible with Creep Hold Times in  
Both Tension and Compression.



27944




27945

Figure 17. Specimen 121C-T-1 - Tensile, Test Temperature - 1832°F Vacuum  
Material - Rene' 80. Top 400X, Bottom 1000X  
Short Time Tensile Fracture Surfaces are Transgranular Ductile  
Rupture Even at High Temperature. Note that Tensile  
Fracture is Associated with Carbide Phases in the Matrix.




27942




27943

Figure 18. Specimen 123C-T-3 - Tensile, Test Temperature - 1600°F Vacuum Material - Rene' 80, Top 400X, Bottom 1000X Short Time Tensile Fracture Surfaces are Transgranular at 1600°F, and Also Associated with Carbide Phases. However, Notice that the Matrix Also Has Multiple Small Dimples (Arrow Typical). Compare with Figure 17.



27939




27940



27941

Figure 19. Specimen 25-C-1 - Creep-Rupture at 1832°F Vacuum  
Material - Rene' 80, Top Left 400X, Top Right 1000X, Bottom 6X.  
Short Time Creep-Rupture (0.7 Hrs., This Specimen) Shows Some  
Evidence of Transgranular Influence (See Slip in 6X Photo),  
but Creep is Evident at Grain Boundaries. It is Interesting to  
Compare the 1000X Surface Texture to the LCF Specimen of Figure 13.



27936



27938



27937

**Figure 20.** Specimen 37U-C-7 - Creep Rupture at 1600°F Vacuum  
Material - Rene' 80. Top Left 400X, Top Right 1000X, Bottom 6X.  
Short Time Creep Rupture (2.1 Hrs. This Specimen) Shows Heavy  
Influence of Transgranular (Slip Planes at Arrow in 1000X Photo  
and 6X Photo) Fracture, But Creep Effects are Very Apparent With  
Grain Boundary Dimpled Structure (Arrow) in 1000X Photo.